




Community Development Department  
Building Division  
120 S. Florida Avenue  
DeLand, Florida 32720  
www.deland.org  
(386) 626-7007

## Thermal Imaging Inspections Now Available!

Warm air leaking into your home or business during the summer and out during the winter simply wastes **your hard earned money!** Our new thermal imaging equipment identifies these problem areas within your home or business. We will provide you with a comprehensive color report outlining the locations where you are losing energy and provide you with our recommendation for the repair. In most cases a combination of air sealing and adding insulation to attics and crawlspaces provides tremendous energy savings and increased comfort.



### Thermal Imaging can identify the following...


- Missing or insufficient insulation in walls, ceilings and attics
- Leaking ducts in HVAC or Heat pump equipment
- Air infiltration around doors and windows
- Overheating electrical components, and much, much more



Thermal Image



Visible Light Image



Thermal Image



Visible Light Image

For additional information please contact Building Division staff at (386) 626-7007 or (386) 626-7009

